



## Green Mountain Food

*Pacific Hydraulics perform a complete hydraulic pump replacement within 24-hours to minimise plant disruption at Green Mountain Food.*

The Greenmountain Group is Australia's largest family owned beef and veal production/processing operation. Situated in Coominya, in the south-east of Queensland, The Greenmountain Group's processing facility delivers a quality product into the domestic and global markets.

Green Mountain Processing had been using a PVH57 Eaton Hydraulic Pump within its meat processing operation since it acquired the processing plant. The pump had seen 2 rebuilds and eventually suffered a major breakdown due to low oil level and a level switch malfunction.

A Pacific Hydraulics Service Technician attended site to assess the situation. Considering the age of the Eaton pump and its suffering of a significant failure, Pacific Hydraulics advised the best course of action was to supply and install a Danfoss Series 45 60cc Hydraulic Pump. The Danfoss replacement unit would provide equivalent shaft, mount and ports, providing an easy change out. Danfoss' pump control is exactly the same as the Eaton PVH57 pump model and interacts perfectly with the current Danfoss PVG32 control valve.

To ensure minimal plant disruption, both the new pump and the Pacific Hydraulics Service Technician were back on site the next morning. The technician performed a complete pump change over and commissioning onsite, getting the associated machinery back up and running in the shortest possible time-frame.

The end result was minimal disruptions and a new Danfoss hydraulic pump which is still operating to maximum efficiency after 4 years of service.



**Company:** Green Mountain Food

**Project:** Repair or replace a failing PVH57 Eaton Hydraulic Pump

**Solutions Proposed:** Supply and installation of a Danfoss Series 45 60cc Hydraulic Pump

**Implementation:** A Pacific Hydraulics Service Technician attended site and performed a complete pump change over and commissioning service

**Special Challenges:** Thanks to the professionalism and skill of the Pacific Hydraulics Technician, the project was completed without any challenges

**Project Outcome:** The Danfoss Series 45 60cc Hydraulic Pump is continuing to operate to maximum efficiency, 4 years after its installation

**Talk to Pacific Hydraulics today to discuss your service and repair needs. Call us on 1800 644 511.**